

This document: Annex 3 – 6 photographs of Aktau Oil Berths

Is a graphic attachment of: Traceca Corridor

**Traffic and Feasibility Studies - tnreg 9803** 

Module E: Transport of crude oil and oil products on

the Caspian Sea

**Technical report: Evaluation of existing facilities** 

(task E2)

January 2001

Both available

on the TRACECA website: www.traceca.org

1. Access way to berths n°4 and n°5



2. Tanker berthed alongside berth n°5 (notice poor piping system)

3. Berth  $\ensuremath{\text{n}^{\circ}5}$  . Details of capping beam, bollards, mooring ropes and fenders

4. Same areas as photo  $\ensuremath{\text{n}}^{\circ}3\,,$  from the front part of the vessel



5. Fire-fighting tower between berths  $n^{\circ}4$  and  $n^{\circ}5$ 



6. Berths n°9 and n°10 (notice low-crested breakwater)

